



## MOORING WINCHES REPORT

<b>SURVEY</b>	<b>TERMINAL GUACOLDA II.</b>
<b>TO</b>	<b>ULTRAMAR AGENCIA MARITIMA</b>
<b>FROM</b>	<b>ALS INSPECTION CHILE SPA.</b>
<b>CLIENT REF</b>	<b>ULTRAMAR AGENCIA MARITIMA</b>
<b>ALS REF</b>	<b>ANF-2605-1783.</b>
<b>SCOPE OF SURVEY</b>	<b>VISUAL INSPECTION OF 7 MOORING WINCHES.</b>
<b>VESSEL NAME</b>	<b>PAN GLOBAL.</b>
<b>PLACE OF SURVEY</b>	<b>HUASCO, BAY.</b>
<b>DATE OF SURVEY</b>	<b>MAY.16, 2026</b>
<b>TIME OF SURVEY</b>	<b>14:30 HRS. TO 17:45 HRS.</b>





## 1.- SURVEY FINDINGS

### 1.1.- Ps, Stern, WINCH



1. View of Ps. stern winch.

2. View of Ps. stern winch.



3. Additional view of Ps. stern winch.



4. View of warping drum/head on Ps. stern winch





## 1.2. Stb, Stern, WINCH



5. View of Stb. stern winch.



6. View of Stb. stern winch.



7. Additional view of Stb. stern winch.



8. View of warping drum.





### 1.3. Spring, Aft, WINCH - BTW H1-H2



9. View of spring Aft. winch BTW H1-H2.



10. View of spring Aft. winch BTW H1-H2.



11. Additional view of spring Aft. winch BTW H1-H2.



12. View of warping drum.





### 1.4.- Ps, Fwd, WINCH



13. View of Ps. Fwd winch.



14. View of Ps. Fwd winch.



15. Additional view of Ps. Fwd winch



16. View of warping drum.





### 1.5.- Stb, Fwd, WINCH



17. View of Stb. Fwd winch.



18. View of Stb, Fwd winch.



19. Additional view of Stb. Fwd winch



20. View of warping drum.





### 1.6.- Stern, ROLLERS & CHOCKS



21. View of Ps. Stern rollers.



22. View of Stb. Stern rollers.



23. View of Ps center Stern rollers.



24. View of Stb center Stern rollers.





25.View of Stern chock.



26.Additional view of Stern chock.



27.View of Stern chock.



28.Additional view of Stern chock,





### 1.7.- Spring, ROLLERS & ROLLER GUIDES



29. View of Spring Btw 1-2 rollers.



30. View of Spring Btw 1-2 rollers.




31. Additional view of Spring Btw 6-7 rollers.



32. Additional view of Spring Btw 6-7 rollers.






33. View of spring Btw 1-2 Pedestal Roller Guide.



34. View of spring Btw 1-3 Pedestal Roller Guide.



35. View of spring Btw 1-3 Pedestal Roller Guide.



36. View of spring Btw 1-2 Pedestal Roller Guide.





### 1.8.- Fwd, ROLLERS & CHOCKS



37. View of Ps. Fwd rollers.



38. View of Stb. Fwd rollers.



39. View of Ps center Fwd rollers



40. View of Stb center Fwd rollers.





41.View of Fwd chock.



42.View of Fwd chock.



43.View of Fwd chock.



44.View of Fwd chock.





## ALS Inspection Chile SpA

Limache 3405, Office 61

Viña del Mar, CHILE

T +56 32 2545 500

Report: ANF-2605-1783

Date: MAY 18, 2026

## 2.- COMMENTS

A **VISUAL INSPECTION** was made to the vessel's winches, rollers and chocks which were observed in good general conditions. This visual inspection is not a guarantee that the winches are in good working order

This survey was carried out without prejudice and in the interest of whom it may concern.

**Surveyor**  
**ALS INSPECTION CHILE SPA**

Prepared by: Daniela Lucero.

Reviewed by: Mauricio Lopez

Approved by: Jaime Lopez

