



MOORING WINCHES REPORT

SURVEY	VISUAL CONDITIONS OF MOORING WINCHES
TO	MR. NICOLAS PALMA.
FROM	ALS INSPECTION CHILE SPA.
CLIENT REF	N/A.
ALS REF	ANF-2605-1973.
SCOPE OF SURVEY	VISUAL INSPECTION OF 08 MOORING WINCHES.
VESSEL NAME	JIN MEI.
PLACE OF SURVEY	CALDERA BAY.
DATE OF SURVEY	JUNE 1, 2026.
TIME OF SURVEY	09:42 HRS, TO 13:30 HRS.





1.- SURVEY FINDINGS

1.1.- Ss, Fwd, WINCH



1. View of Ss, Fwd, winch.



2. View of Ss, Fwd, winch.



3. Another view as previous one.



4. View of warping drum.





1.2.- Mid, Fwd, WINCH



5. View of Mid, Fwd, winch.



6. View of Mid, Fwd, winch.



7. View of Mid, Fwd, winch



8. View of winch for brest line.





1.3.- Ps, Fwd, WINCH



9. View of Ps, Fwd, winch.



10. View of Ps, Fwd, winch.



11. Another view as previous one.



12. View of warping drum.





1.4.- WINCH BETWEEN H2 & H3



13. View of winch Between H2 & H3.



14. View of winch Between H2 & H3.



15. Another view as previous one.



16. View of warping drum.





1.5.- WINCH BETWEEN H8 & H9



17.View of winch Between H8 & H9.



18.View of winch Between H8 & H9.



19.Another view as previous one.



20.View of winches.





1.6.- Ss, Aft, WINCH



21.View of Ss, Aft, winch.



22.View of Ss, Aft, winch.



23.Another view as previous one.



24.View of warping drum.





1.7.- Mid, AFT, WINCH



25.View of Mid, Aft, winch.

26.View of Mid, Aft, winch.



27.Another view as previous one.

28.View of warping drum.





1.8.- Ps, Aft, WINCH



29.View of Ps, Aft, winch.



30.View of Ps, Aft, winch.



31.Another view as previous one



32.View of warping drum.





1.9.- Stern, ROLLERS & CHOCKS



33. View of Ps. Stern rollers.



34. View of Stb. Stern rollers.



35. View of Ps center Stern rollers.



36. View of Stb center Stern rollers.





1.10.- Spring, ROLLERS & ROLLER GUIDES



37.View of Spring Btw 8-9 rollers.



38.View of Spring Btw 8-9 rollers.



39.Additional view of Spring Btw 2-3 rollers.



40.Additional view of Spring Btw 2-3 rollers.





41. View of spring Btw 8-9 Pedestal Roller Guide.



42. View of spring Btw 8-9 Pedestal Roller Guide.



43. View of spring Btw 8-9 Pedestal Roller Guide.



44. View of spring Btw 8-9 Pedestal Roller Guide.





45. View of spring Btw 3-2 Pedestal Roller Guide.



46. View of spring Btw 3-2 Pedestal Roller Guide.



47. View of spring Btw 3-2 Pedestal Roller Guide.



48. View of spring Btw 3-2 Pedestal Roller Guide.





1.11.- Fwd, ROLLERS & CHOCKS



49. View of Ps. Fwd rollers.



50. View of Stb. Fwd rollers.



51. View of Ps center Fwd rollers



52. View of Stb center Fwd rollers.





53.View of Fwd chock.



54.View of Fwd chock.



55.View of Fwd chock.



56.View of Fwd chock.





2.- COMMENTS

A **visual inspection** was made to the vessel's winches, which were observed in good general conditions. This visual inspection is not a guarantee that the winches are in good working order.

This survey was carried out without prejudice and in the interest of whom it may concern.

ALS INSPECTION CHILE SPA

Prepared by: D. Lucero.

Reviewed by: M. Lopez.

Validated by: J. Lopez.

