

FEBRUARY 11st, 2026

CPA-2602-0598.,

Inspection Report

SERVICES			
Sampling	-	Port Control	-
Weighing	-	Reception	-
Moisture Determination	-	Stuffing	-
Samples preparation	-	Other (Stock Inspection + HC)	✓

GENERAL INFORMATION	
Client	: Ocean Partners UK Ltd
Clients reference	: ZU5T586
ALS Reference	: CPA-2602-0598
Place of Inspection	: Contopsa inland terminals
Date of Attendance	: FEBRUARY 11 st , 2026
Material	: Secondaries Copper Concentrates B3 (perfilado de piso).
Surveyor	: ALS Inspection Chile SpA
Inspector	: Constanza Valladares

Scope

- As requested by our client Ocean Partners UK Ltd, our company was appointed to perform visual inspection, to check the stock of goods declared as secondaries copper concentrates B3 (perfilado de peso).
- According to the inspection, the amount of material was visually verified on the facilities.

Visual Inspection

- The material consists of a collection of **rocks and mineral fragments of various sizes**, stored in what appears to be an industrial stockpile. The overall appearance suggests that it may be **metallic slag, crushed mineral, or raw rock**, based on its irregular shape and dusty surface.
- The predominant color is a **dull gray**, with some fragments showing **greenish or gray-green tones**, likely due to oxidation or specific mineral content. Several areas are covered with **light gray fine dust**, giving the material a matte, low-reflective appearance.
- The texture is **very rough and irregular**, typical of fractured rock or industrial by-products from smelting processes. Some pieces appear **porous**, while others are **dense and compact**. The surfaces are coated with **loose dust**, and many fragments show **broken or sharp edges**.
- **Estimated Particle Size Range**
 - **Large fragments:** Approximately **10 cm to 40 cm** ($\approx 4''$ to $16''$)
 - **Medium fragments:** Approximately **3 cm to 10 cm** ($\approx 1''$ to $4''$)
 - **Fine fragments:** **Less than 1 cm** ($\approx < 0.4''$)



FEBRUARY 11st, 2026

CPA-2602-0598.,

CPA-2602-0598.,

➤ **Shape Characteristics**

- The fragments show **irregular, angular shapes**, with sharp or fractured edges. They do not appear to be manufactured pieces, but rather **natural or residual material** resulting from breakage or industrial processing.
- Piles are located in a covered warehouse with concrete floor at Contopsa inland terminals, San Antonio-Chile

Weight (as declared)

Quantity (MT) Secondaries Copper Concentrates B3
3.354,720



FEBRUARY 11st, 2026

CPA-2602-0598.,



JOSE GALAN TRUJILLO ALIAGA
Gerente de Operaciones Minerales
ALS Inspection Chile

