



## MOORING WINCHES REPORT

<b>SURVEY</b>	<b>VISUAL CONDITIONS OF MOORING WINCHES</b>
<b>TO</b>	MR. JULIO OLIVERO.
<b>FROM</b>	ALS INSPECTION CHILE SPA.
<b>CLIENT REF</b>	N/A.
<b>ALS REF</b>	ANF-2601-0118.
<b>SCOPE OF SURVEY</b>	VISUAL INSPECTION OF 8 MOORING WINCHES.
<b>VESSEL NAME</b>	FRONTIER NEIGE.
<b>PLACE OF SURVEY</b>	CALDERA BAY.
<b>DATE OF SURVEY</b>	JANUARY 10, 2026.
<b>TIME OF SURVEY</b>	15:34 HRS, TO 19:38 HRS.



## 1.- SURVEY FINDINGS

### 1.1.- Ss, Fwd, WINCH



1. View of Ss, Fwd, winch.

2. View of Ss, Fwd, winch.



3. Another view as previous one.

4. View of warping drum.




## 1.2.- Ps, Fwd, WINCH



1. View of Mid, Fwd, winch.

2. View of Mid, Fwd, winch.



3. View of Mid, Fwd, winch

4. View of winch for brest line.



### 1.3.- WINCH BETWEEN H8 & H9



1. View of winch Between H8 & H9.



2. View of winch Between H8 & H9.



3. Another view as previous one.



4. View of warping drum.



### 1.4.- WINCH BETWEEN H2 & H3



1. View of winch Between H2 & H3.

2. View of winch Between H2 & H3.



3. Another view as previous one.

4. View of warping drum.



### 1.5.- WINCH BETWEEN H1 & H2



1. View of winch Between H1 & H2.



2. View of winch Between H1 & H2.



3. Another view as previous one.



4. View of winches.



### 1.6.- Ss, Aft, WINCH



1. View of Ss, Aft, winch.



2. View of Ss, Aft, winch.



3. Another view as previous one.



4. View of warping drum.



### 1.7.- Mid, AFT, WINCH



1. View of Mid, Aft, winch.



2. View of Mid, Aft, winch.



3. Another view as previous one.



4. View of warping drum.



### 1.8.- Ps, Aft, WINCH



1. View of Ps, Aft, winch.



2. View of Ps, Aft, winch.



3. Another view as previous one



4. View of warping drum.



## 2.- COMMENTS

A **visual inspection** was made to the vessel's winches, which were observed in good general conditions. This visual inspection is not a guarantee that the winches are in good working order.

This survey was carried out without prejudice and in the interest of whom it may concern.

### ALS INSPECTION CHILE SPA

Prepared by: D. Lucero.

Reviewed by: M. Lopez.

Validated by: J. Lopez.