



FINAL REPORT

SURVEY	MOORING ROPES INSPECTION
TO	GUAYACAN TERMINAL
FROM	ALS INSPECTION CHILE SPA.
CLIENT REF	N/A
ALS REF	VAP-2605-1839
SCOPE OF SURVEY	INSPECTION OF 18 MOORING LINES.
VESSEL NAME	PIGI
OWNER	OLYMPIAN CORAL MARINE LTD.
DISPONENT OWNER	EAST 33 MARITIME LTD.
CHARTERERS	CLASSIC MARITIME INC.
PLACE OF SURVEY	COQUIMBO BAY
DATE OF SURVEY	MAY 19, 2026
TIME OF SURVEY	FROM 02:00 HRS TO 05:20 HRS

SUMMARY

From a total of 18 mooring lines inspected:

- All of them COMPLY with the length and visual condition for use.

Definitions:

Good : Unimpaired condition without significant wear or deviation from original strength and operating efficiency.

Fair : Condition in which wear and tear and other deficiencies of minor nature not requiring correction or repair.

Poor : Condition in which the adequacy of strength and/or operational efficiency is marginally below acceptable limits or is in doubt.



1.- SURVEY FINDINGS

1.1.- CHECK LIST OF MOORING ROPE N° 1

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001056

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 226.3 meters.

Remarks: N/A



1. General view of the rope.



2. Diameter of the rope.



3. Measurement of the rope,
226.3 meters.



4. Seal Nr. 0001056.



1.2.- CHECK LIST OF MOORING ROPE N° 2

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001057

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 231.6 meters.

Remarks: N/A



5. General view of the rope.



6. Diameter of the rope.



7. Measurement of the rope,
231.6 meters.



8. Seal N° 0001057.



1.3.- CHECK LIST OF MOORING ROPE N° 3

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001058

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 234.3 meters.

Remarks: N/A



9. General view of the rope.



10. Diameter of the rope.



11. Measurement of the rope,
234.3 meters.



12. Seal N° 0001058.



1.4.- CHECK LIST OF MOORING ROPE N° 4

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001059

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 231.6 meters.

Remarks: N/A



13. General view of the rope.



14. Diameter of the rope.



15. Measurement of the rope,
231.6 meters.



16. Seal N° 0001059.



1.5.- CHECK LIST OF MOORING ROPE N° 5

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	NISEKO QUEEN / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001060

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 231.9 meters.

Remarks: N/A



17. General view of the rope.



18. Diameter of the rope.



19. Measurement of the rope,
231.9 meters.



20. Seal N° 0001060.



1.6.- CHECK LIST OF MOORING ROPE N° 6

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001061

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 224.2 meters.

Remarks: N/A



21. General view of the rope.



22. Diameter of the rope.



23. Measurement of the rope,
224.2 meters.



24. Seal N° 0001061.



1.7.- CHECK LIST OF MOORING ROPE N° 7

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001062

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 221.3 meters.

Remarks: N/A



25. General view of the rope.



26. Diameter of the rope.



27. Measurement of the rope,
221.3 meters.



28. Seal N° 0001062



1.8.- CHECK LIST OF MOORING ROPE N° 8

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001063

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 232.4 meters.

Remarks: N/A



29. General view of the rope.



30. Diameter of the rope.



31. Measurement of the rope,
232.4 meters.



32. Seal N° 0001063



1.9.- CHECK LIST OF MOORING ROPE N° 9

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001064

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 226.4 meters.

Remarks: N/A



33. General view of the rope.



34. Diameter of the rope.



35. Measurement of the rope,
226.4 meters.



36. Seal N° 0001064.



1.10.- CHECK LIST OF MOORING ROPE N° 10

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001065

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 226.5 meters.

Remarks: N/A



37. General view of the rope.



38. Diameter of the rope.



39. Measurement of the rope,
226.5 meters.



40. Seal N° 0001065.



1.11.- CHECK LIST OF MOORING ROPE N° 11

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001066

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 232.1 meters.

Remarks: N/A



41. General view of the rope.



42. Diameter of the rope.



43. Measurement of the rope,
232.1 meters.



44. Seal N° 0001066.



1.12.- CHECK LIST OF MOORING ROPE N° 12

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001067

According OCIMF standard, letter D.2 / Cordage Institute DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 232.9 meters.

Remarks: N/A



45. General view of the rope.



46. Diameter of the rope.



47. Measurement of the rope,
232.9 meters.



48. Seal N° 0001067.



1.13.- CHECK LIST OF MOORING ROPE N° 13

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001068

According OCIMF standard, letter D.2 / Cordage Institute & DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 225.6 meters.

Remarks: N/A



49. General view of the rope.



50. Diameter of the rope.



51. Measurement of the rope,
225.6 meters.



52. Seal N° 0001068.



1.14.- CHECK LIST OF MOORING ROPE N° 14

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001069

According OCIMF standard, letter D.2 / Cordage Institute & DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 222.2 meters.

Remarks: N/A



53. General view of the rope.



54. Diameter of the rope.



55. Measurement of the rope,
222.2 meters.



56. Seal N° 0001069.



1.15.- CHECK LIST OF MOORING ROPE N° 15

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001070

According OCIMF standard, letter D.2 / Cordage Institute & DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 229.6 meters.

Remarks: N/A



57. General view of the rope.



58. Diameter of the rope.



59. Measurement of the rope,
229.6 meters.



60. Seal N° 0001070.



1.16.- CHECK LIST OF MOORING ROPE N° 16

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001071

According OCIMF standard, letter D.2 / Cordage Institute & DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 225.6 meters.

Remarks: N/A



61. General view of the rope.



62. Diameter of the rope.



63. Measurement of the rope,
225.6 meters.



64. Seal N° 0001071.



1.17.- CHECK LIST OF MOORING ROPE N° 17

ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001072

According OCIMF standard, letter D.2 / Cordage Institute & DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 229.5 meters.

Remarks: N/A



65. General view of the rope.



66. Diameter of the rope.



67. Measurement of the rope,
229.5 meters.



68. Seal N° 0001072.



1.18.- CHECK LIST OF MOORING ROPE N° 18


ALS REFERENCE	VAP-2605-1839	Date/Time	19/05/2026
CLIENT	ULTRAMAR		
VESSEL/PLACE	PIGI / COQUIMBO, CHILE.		
MOORING ROPE NOMINAL LENGHT	220 METERS	SEAL APPLIED	ALS 0001073

According OCIMF standard, letter D.2 / Cordage Institute & DIRSOMAR-PROINSP/200/011/2016

DAMAGE ITEM	GOOD	FAIR	POOR
Ext. Abrasion (max 25%)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Over 25% <input type="checkbox"/>
Int. Abrasion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cut strands	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Burn/ heated parts / fusion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sun degradation /discoloration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fiber broken	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Black stains / dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inconsistent diameter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inconsistent flexibility	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Number of splices	(0) <input checked="" type="checkbox"/>	(1- 2) <input type="checkbox"/>	Discard 3 <input type="checkbox"/>

Length measured by surveyor: 228.5 meters.

Remarks: N/A



69. General view of the rope.



70. Diameter of the rope.



71. Measurement of the rope,
228.5 meters.



72. Seal N° 0001073.



2.- COMMENTS

It is important to mention that upon our inspection of the mooring lines, these were not arranged in their entire length, even though they were measured 2 times to achieve an average measurement.

No records of history of previous inspections of the mooring lines were shown, nor did the units possess visible or recognizable identification such as plates, sleeves, seals, or permanent marks.

The mooring ropes corresponding to standard ropes. According to information received from Vessel Chief officer the vessel does not use mooring tails.

Visual inspection of mooring ropes was carried out with artificial light and two surveyors.

From a total of 18 mooring lines inspected, all of them comply with the conditions for use.

This survey was carried out without prejudice and in the interest of whom it may concern.

Surveyor
ALS INSPECTION CHILE SPA

Prepared by : V. Alfaro

Reviewed by : C. Alvear

Validated by : J. Lopez