



ALS Inspection Chile SpA

Limache 3405, Office 61

Viña del Mar, CHILE

T +56 32 2545 500

Report: SAI-2603-0918

Date: March 06, 2026

LASHING CERTIFICATE

ALS INSPECTION CHILE SpA prepared this certificate under requirement of Messrs. **Loginter Ltda.,** Mr. Sebastian Gatica.

ALS Certificate Nr. : SAI-2603-0918

Date of inspection : March 05, 2026
Place of inspection : El Naranjo Lote 42 Parcela 79, Curacaví - Chile.
Container : **HLBU 817133-9 / 1 x 40' FR**
Characteristics : Gross Wt: 60,000 kg // Tare: 6,000 kg // Net Wt: 54,000 kg

Cargo:

	LENGTH m	WIDTH m	HEIGHT m	GW Kg
1 WOODEN CRATE (Packing List 50065382)	2.44	2.44	0.61	593.00
1 WOODEN CRATE (Packing List 50065382)	2.44	2.44	0.61	593.00
1 WOODEN CRATE (Packing List 50065382)	2.44	2.44	0.61	593.00
1 WOODEN CRATE (Packing List 50065288)	2.44	2.44	0.63	610.00
1 WOODEN CRATE (Packing List 50065352)	2.44	2.44	0.63	610.00
1 WOODEN CRATE (Packing List 50065351)	2.44	2.44	0.63	610.00
1 WOODEN CRATE (Packing List 50065289)	2.44	2.44	0.63	610.00
1 WOODEN CRATE (Packing List 50065352)	2.44	2.44	0.63	610.00
1 WOODEN CRATE (Packing List 50065386)	2.44	2.44	0.63	603.00

Total Tonnage : Gross 5,432.00 kg.
Shipper : C. H. Robinson.
Address : Los Militares 5001, piso 10, Las Condes.
Type of lashing : 13 units of synthetic flat slings, with a LC of 1167 Kg., 26 units of shackles with a WLL of 3 ¼ tns. 4x4" Square lumbers used for chocking. All edges were the sling pass over, were duly protected with rubber pieces.
Port of loading : San Antonio - Chile.
Port of discharge : Los Angeles - U.S.A.

The cargo lashing was carried out by LOGINTER staff according to local and international practices for this kind of cargo, with special consideration and fully compliant with IMO Code of Safe Practice for Cargo Stowage and Securing, and IMO/ILO/UN ECE Guidelines for Packaging of Cargo Transport Units (CTUs)

Conclusion: According to our inspection and experience, the cargo securing complies with the international standards and IMO Code of Safe Practice for Cargo Stowage and Securing, provided that the lashing is checked on a regular basis, and tightened when necessary by the vessel's staff.

ISAAC COHEN
SURVEYOR
ALS INSPECTION CHILE



Preparado por	ISAAC COHEN		
Revisado y aprobado por	CLAUDIO ALVEAR	Informe nº	SAI-2603-0918
Formulario	FO-7-05-41 Lashing Certificate	Versión	# 01 - 11/11/2014



SET OF PHOTOS



1. Flat rack container N° HLBU 817133-9



2. Identifications and characteristics of container.



3. Container CSC Plate.



4. Slings thickness of 50mm.

Preparado por	ISAAC COHEN		
Revisado y aprobado por	CLAUDIO ALVEAR	Informe n°	SAI-2603-0918
Formulario	FO-7-05-41 Lashing Certificate	Versión	# 01 - 11/11/2014



5. Sling capacity, 1750 kg WLL.



6. Rubber protection places on sharp edges.



7. Rubber protection places on sharp edges.



8. Shackles of 5/8 used to fit the sling hooks on container ringbolts. WLL 3 ¼ ton.

Preparado por	ISAAC COHEN		
Revisado y aprobado por	CLAUDIO ALVEAR	Informe nº	SAI-2603-0918
Formulario	FO-7-05-41 Lashing Certificate	Versión	# 01 - 11/11/2014



9. Crates were checked by means square lumbers.



10. Crates were checked by means square lumbers.



11. Square lumbers with fumigation stamp.



12. Other view.

Preparado por	ISAAC COHEN	Informe n°	SAI-2603-0918
Revisado y aprobado por	CLAUDIO ALVEAR	Versión	# 01 - 11/11/2014
Formulario	FO-7-05-41 Lashing Certificate		



13. Final view of cargo stowage and lashed over the container.



14. Other view.

Preparado por	ISAAC COHEN		
Revisado y aprobado por	CLAUDIO ALVEAR	Informe n°	SAI-2603-0918
Formulario	FO-7-05-41 Lashing Certificate	Versión	# 01 - 11/11/2014