



ALS Inspection Chile SpA  
 Limache 3405, Office 61  
 Viña del Mar, CHILE  
 T +56 32 2545 500

Report: THO-2511-2475  
 Date: November 30 ,2025

## HOLDS UN-SEALING CERTIFICATE

**M/V : GENCO RHONE**

IMO Number : 9490832

Flag. : MARSHALL ISLANDS

Port. : PORTUARIA CABO FROWARD-CORONEL/ CHILE.

This is to certify that following seals have been fitted on holds access before start unloading operation.

| Hold Nr.    | 1               | Hold Nr.    | 2               |
|-------------|-----------------|-------------|-----------------|
| Hatch cover | 049324          | Hatch cover | 049326          |
| Manhole     | 049323 / 049325 | Manhole     | 049327 / 049328 |
| Hold Nr.    | 3               | Hold Nr.    | 4               |
| Hatch cover | 049329          | Hatch cover | 049332          |
| Manhole     | 049330 / 049331 | Manhole     | 049333 / 049334 |
| Hold Nr.    | 5               |             |                 |
| Hatch cover | 049335          |             |                 |
| Manhole     | 049336 / 049337 |             |                 |

Seals fitted on hatch covers and Stevedore's access.

  
  
**Héctor Campos C.**  
**ALS INSPECTION CHILE**  
**SURVEYOR**

  
**M.V. GENCO RHONE**  
  
**Chief Officer**

**Chief Officer**  
**MV GENCO RHONE**

**FOR RECEIPT ONLY,**  
**WITHOUT PREJUDICE.**