



ALS Inspection Chile SpA
Limache 3405, Office 61
Viña del Mar, CHILE
T +56 32 2545 500

Report: IQ-2602-0793

Date: March 04th, 2026

Port Caleta Patillos, CHILE.

**To the Master/Chief Officer
MV SPL TARAPACA**

Dear Sir,

This is to inform you that we have been appointed to determine the loaded/discharged cargo by means of a Draft Survey. Therefore, we require your vessel cooperation with the following:

1. **Upright**- e.g. without list
2. **Trim by the stern and not more than 1% of the length or as close as possible.** [Trim not by the bow]
3. **Ballast tanks full by overflowing, empty or minimum possible.**
4. **No shifting of ballast is allowed throughout the draft survey.**
5. **Provide with the Bunker quantity updated at the time of the draft survey performing.**
6. **Do not carry out movements of cranes or hatch covers during draft readings.**

Any failure to comply with these requirements **may cause delays to the vessel loading/discharged operations.**

Kind Regards,

Miguel Cortés Fuentes
Surveyor
ALS
INSPECTION




Chief Officer
MV SPL TARAPACA

