



This is to certify what we, **ALS Inspection CHILE SpA** did, at the request of Messrs. **Ecos Muellaje** stevedores, the undersigned surveyor attended onboard:

"M/V HERMES LEADER"

On February 27, While the vessel was berthed alongside pier Nr. 2, Empresa Portuaria de Iquique (EPI/Iquique/CHILE), for the purpose of carrying out an:

"Arrival Condition Certificate"

Brand	Chassis	Observation
NISSAN	014567	Scratched front bumper, used
TOYOTA	002858	Scratched left front bumper, used
TOYOTA	022727	Scratched front bumper, used
TOYOTA	134303	Dented front bumper, used
TOYOTA	169730	Without radio, used
MAZDA	102386	Scratched left rear door, used
TOYOTA	002919	Scratched front bumper, used
TOYOTA	027486	Dented left rear fender, used
TOYOTA	025745	Chopped windshield, used
TOYOTA	404283	Without radio, used
TOYOTA	059028	Dented left rear fender, used
TOYOTA	092178	Scratched left front bumper, used
TOYOTA	125548	Dented left rear fender, used
TOYOTA	124945	Dented left side, used
NISSAN	221068	Dented left rear fender, used
TOYOTA	015515	Scratched front bumper, used
TOYOTA	301372	Without radio, used
HONDA	002142	Without Knob, used
TOYOTA	065158	Scratched left rear door, used
TOYOTA	076449	Broken left front bumper, used
TOYOTA	007810	Broken left front bumper, used
TOYOTA	027211	Dented left front door, used
TOYOTA	003194	Scratched left rear door, used
TOYOTA	097956	Dented left side, used
NISSAN	011471	Front door left side dented
TOYOTA	075028	Scratched front bumper, used
TOYOTA	022897	Chopped windshield, used
HONDA	009232	Chopped windshield, used
TOYOTA	009740	Scratched left front bumper, used



TOYOTA	027030	Scratched front bumper, used
TOYOTA	104786	Dented left rear fender, used
SUBARU	102532	Dented left rear fender, used
SUZUKI	318453	Broken right front bumper, used
LEXUS	014161	Scratched 5° Door to arrival condition, new
TOYOTA	086809	Scratched front bumper, used
NISSAN	099765	Dented 5° door, used

ALS Inspections Remarks: ALS Inspections inspected all the cargo on board. This Arrival Certificate only shows those new and second hand vehicles that arrived with some observations during our inspection.

Chief Officer's Remark:



GONZALO BACIAN VALDIVIA
Surveyor
ALS INSPECTION CHILE SpA



"M/V HERMES LEADER V - 080"
Chief Officer

ALL UNITS DISCHARGED
IN THE SAME CONDITION
AS LOADED.