

1. SCOPE OF SURVEY

To perform a visual inspection to the condition of 17 mooring lines, measure its length and diameter, on board of **MV. MERCHANT MARINER** at the CALDERA, BAY

2. TIMES:

ITEM	FECHA	HORA
ALS Surveyor arrives to inspection place	07/05/2026.	15:32
Start Inspection of the 17 mooring lines on board the vessel		15:50
Inspection completed		18:45
ALS surveyor left the vessel		19:40

3. INSPECTION

Below is a detail and observations of the mooring lines inspected:

ITEM	POSITION	MEASUREMENTS		SEAL ALS	OBSERVATIONS
		LENGTH (m)	DIAMETER (mm)		
1	STERN	220,7	69,0	0000721	ACCEPTED.
2	STERN	220,5	69,0	0000722	ACCEPTED.
3	STERN	220,7	69,0	0000723	ACCEPTED.
4	STERN	221,0	67,0	0000724	ACCEPTED.
5	BETWEEN 08/09	220,5	69,0	0000725	ACCEPTED.
6	BETWEEN 08/09	220,4	69,0	0000726	ACCEPTED.
7	BETWEEN 02/03	220,6	69,0	0000727	ACCEPTED.
8	BETWEEN 02/03	220,5	69,0	0000728	ACCEPTED.
9	BOW	220,7	69,0	0000729	ACCEPTED.
10	BOW	220,5	69,0	0000730	ACCEPTED.
11	BOW	220,4	69,0	0000731	ACCEPTED.

ALS Inspection Chile SpA

Limache 3405, Office 61
Viña del Mar, CHILE
T +56 32 2545 500

Report: ANF-2605-1730.

Date: May 07, 2026.

12	BOW	220,6	69,0	0000732	ACCEPTED.
13	BOW	220,0	69,0	2920736	REJECTED.
14	BOW	220,0	69,0	2920737	REJECTED.
15	STERN	220,0	85,0	0000733	ACCEPTED.
16	STERN	220,1	82,0	0000734	ACCEPTED.
17	IN CASE OF EMERGENCY	222,3	62,0	0000735	ACCEPTED.

4. COMMENTS

No records or history of previous inspections of the mooring lines from ALS company were shown, not did the units possess visible or recognizable identification such as plates, sleeves, seals, or permanent marks from ALS company, Caldera, Chile.

The mooring ropes corresponding to standard ropes. According to information received from Vessel Chief officer the vessel does not use mooring tails.

5. CONCLUSIONS

From a total of 17 mooring lines inspected, 15 of them comply with the conditions for use.

This survey was carried out without prejudice and in the interest of whom it may concern.


DANIELA LUCERO
ALS INSPECTION CHILE Spa


MASTER OR CHIEF OFFICER
MV. MERCHANT MARINER



Prepared by: Daniela Lucero Tudesca.

PRELIMINARY REPORT

TO	TERMINAL TOTORALILLO.
FROM	ALS INSPECTION CHILE SPA
PRELIMINARY ISSUE DATE	MAY 07, 2026.
CLIENT REF	N/A
ALS REF	ANF-2605-1730.
SCOPE OF SURVEY	INSPECTION OF 17 MOORING LINES.
VESSEL NAME	MERCHANT MARINER
PLACE OF SURVEY	CALDERA, BAY.
DATE OF SURVEY	MAY 07 ,2026.
TIME OF SURVEY	15:50 HRS. TO 18:45 HRS.
Please find our preliminary report; this should be taken as an initial approach of the appointed inspection. Additional information, findings, photographs, and conclusions will be part of our final report.	

SURVEYOR'S COMMENTS
From a total of 17 mooring lines inspected: - 15 COMPLY with the length and visual condition for use. - 02 Rejected due to abrasion and strands cutting.