



## Hold's pre-loading inspection Certificate

<b>Vessel Name</b>	<b>EVER ALLIANCE</b>	<b>Port of Survey</b>	Caleta Patillos
<b>Cargo to be loaded</b>	Salt in Bulk	<b>Voyage Nr.</b>	094
<b>Report Nr.</b>	<b>IQQ-2602-0798</b>	<b>Date</b>	March 17 <sup>th</sup> , 2026

A	Hatch covers and hatch coamings	Yes	Not	Good	Fair	Poor
a.1	General appearance's condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.2	Are there any steel damages in the folders or	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.3	Rubber packing condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.4	Are there any sign of sealing tape??	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.5	Opening/closing systems condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.6	Are there signs of lube oil leaks from hydraulic	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.7	Acting cleats condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.8	Compression bar condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.9	Track way, rollers condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.10	Are the non-return valves of coamings operative??	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.11	Are the drainage of coamings free??	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
B	Cargo Hold Number: 1, 3 & 4	Yes	Not	Good	Fair	Poor
b.1	Cleanliness condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.2	Are there any signs of previous cargoes??	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.3	Are there any signs of living insects??	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.4	Are there any signs of water??	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.5	Are there any signs of lube oil leaks??	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.6	Are there any signs of loose paint??	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.7	Are there any signs of rust scale loose??	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.8	Are there any problems or damages on access	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.9	Lighting condition ( <b>Artificial light</b> )	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.10	Are the holds free of odor (hydrocarbon)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.11	Are the scuppers free of garbage??	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.12	Are the bilges dry and clean??	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>



<b>C</b>	<b>Additional information</b>		
<b>c.1</b>	Last watertight test (date)	January 21 <sup>st</sup> , 2026	
<b>c.2</b>	Certificate of load line date	Issued: December 29 <sup>th</sup> , 2025	Valid until: February 13 <sup>th</sup> , 2031
<b>c.3</b>	Last three (3) cargoes transported	1.- Sulphur (Last Cargo) 2.- Coal 3.- Clinker cement	

**NOTES**

➤ **First holds Inspection (from March 15<sup>th</sup>, 2026 / from 00:45 to 01:35 LT).**

The holds Nr. 1, 2, 3, 4 & 5 were found with rest of previous cargoes Sulphur, dust of previous cargo on bulkhead, hooper tank and between frames.

Holds were rejected not in condition to be load salt.

➤ **Second holds Inspection (from March 16<sup>th</sup>, 2026 / from 20:45 to 21:10 LT).**

The holds Nr. 1, 3 & 4 were found clean and dry in condition to be white washed.

➤ **Third holds Inspection (from March 17<sup>th</sup>, 2026 / from 00:50 to 01:15 LT).**

Holds 1, 3 & 4 were found clean, dry and white washed.

Holds were accepted in condition to be load salt.



0363325563771

**Miguel Cortés Fuentes**  
**ALS INSPECTION CHILE**

