



Holds pre-loading inspection Certificate

Vessel Name	OCEAN DILIGENCE	Port of Survey	Caleta Patillos
Cargo to be loaded	Salt in Bulk	Voyage Nr.	018
Report Nr.	IQQ-2601-0036	Date	January 17 th , 2026

A	Hatch covers and hatch coamings	Yes	Not	Good	Fair	Poor
a.1	General appearance's condition	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
a.2	Are there any steel damages in the folders or	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.3	Rubber packing condition	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
a.4	Are there any sign of sealing tape??	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.5	Opening/closing systems condition	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
a.6	Are there signs of lube oil leaks from hydraulic	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.7	Acting cleats condition	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
a.8	Compression bar condition	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
a.9	Track way, rollers condition	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
a.10	Are the non-return valves of coamings operative??	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a.11	Are the drainage of coamings free??	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
B	Cargo Hold Number: 1, 2, 3, 4 & 5	Yes	Not	Good	Fair	Poor
b.1	Cleanliness condition	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
b.2	Are there any signs of previous cargoes??	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.3	Are there any signs of living insects??	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.4	Are there any signs of water??	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.5	Are there any signs of lube oil leaks??	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.6	Are there any signs of loose paint??	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.7	Are there any signs of rust scale loose??	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.8	Are there any problems or damages on access	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.9	Lighting condition (Natural light)	<input type="checkbox"/>	<input type="checkbox"/>	X	<input type="checkbox"/>	<input type="checkbox"/>
b.10	Are the holds free of odor (hydrocarbon)	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.11	Are the scuppers free of garbage??	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b.12	Are the bilges dry and clean??	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>



C	Additional information		
c.1	Last watertight test (date)	January 14 th , 2026	
c.2	Certificate of load line date	Issued: January 02 nd , 2024	Valid until: January 01 st , 2029
c.3	Last three (3) cargoes transported	1.- Coal (Last Cargo) 2.- Rock Salt 3.- Coal	

NOTES

➤ **First holds Inspection (from January 15th, 2026 / from 13:15 to 14:30 LT).**

The holds Nr. 1, 2, 3, 4 & 5 were found with rest of previous cargoes, (coal dust of previous cargoes).

➤ **Second holds Inspection (from January 16th, 2026 / from 18:10 to 19:00 LT).**

The holds Nr. 1, 2, 3, 4 & 5 were found clean and dry in condition to be white washed.

➤ **Third holds Inspection (from January 17th, 2026 / from 14:15 to 14:55 LT).**

Holds 1, 2, 3 4 & 5 were found clean, dry and white washed.

Holds were accepted in condition to be load salt.

*For receipt only
without acceptance of
first hold inspection report/statement.*



Miguel Cortés Fuentes
ALS INSPECTION CHILE



Captain
MV OCEAN DILIGENCE