

January 16<sup>TH</sup>, 2025

CPA-2601-0200

# Inspection Report

SERVICES			
Sampling	-	Port Control	-
Weighing	-	Reception	-
Moisture Determination	-	Stuffing	-
Samples preparation	-	Other (Stock Inspection + HC)	✓

GENERAL INFORMATION	
Client	: Ocean Partners chile spa
Clients reference	: P 91809.08
ALS Reference	: CPA-2601-0200
Place of Inspection	: Logec El Turco
Date of Attendance	: January 16 <sup>TH</sup> , 2025
Material	: Gold Concentrate
Surveyor	: ALS Inspection Chile SpA
Inspector	: Christian Letelier

## Scope

- As requested by our client Ocean partners Chile Spa , our company was appointed to perform visual inspection, to check the stock of goods declared as Au Cons
- According to the inspection, the amount of material was visually verified on the facilities.

## Visual Inspection

- Material was observed yellow in color, with an homogenic appearance and it was held stored in one (01) pile, located at Warehouse N°3
- Piles are located in a covered warehouse with concrete floor at Logec El Turco, San Antonio-Chile

## Weight (as declared)

Amount (MT) As declared
7.860

JOSE GALAN TRUJILLO ALIAGA  
Gerente de Operaciones Minerales

**ALS Inspection Chile**





January 16<sup>TH</sup>, 2025

CPA-2601-0200

**Material stored at Warehouse N °3**

