



ALS Inspection Chile SpA
 Limache 3405, Office 61
 Viña del Mar, CHILE
 T +56 32 2545 500
 Ref: THO-2603-1173

SEALING CERTIFICATE


M/V : ARGOS REEFER
 IMO Number : 9184548
 Flag : BAHAMAS
 Port : TALCAHUANO / CHILE
 Date : APRIL 13, 2026

This is to certify that following seals have been fitted on Cooling Room, Hatch Covers and Manholes covers upon loading completed.

Hold Nr.	1	Hold Nr.	2
Hatch cover	92301 / 92302	Hatch cover	92310 / 92311
Manhole cover	92303	Manhole cover	92312
Cooling Room Door A	92304	Cooling Room Door A	92313
Cooling Room Door B	92305 / 92306 / 92307	Cooling Room Door B	92314
Cooling Room Door C	92308 / 92309	Cooling Room Door C	92315 / 92316 / 92317
-	-	Cooling Room Door D	92318 / 92319

Hold Nr.	3	Hold Nr.	4
Hatch cover	92320 / 92321	Hatch cover	92330 / 92331
Manhole cover	92322	Manhole cover	92332
Cooling Room Door A	92323	Cooling Room Door A	92333
Cooling Room Door B	92324	Cooling Room Door B	92334
Cooling Room Door C	92325 / 92326 / 92327	Cooling Room Door C	92335 / 92336 / 92337
Cooling Room Door D	92328 / 92329	Cooling Room Door D	92338 / 92339

Seals fitted on hatch covers, cooling room and manholes covers.


Mr. Daniel Vargas.
 ALS Inspection Chile
 Surveyor



Master or C/O
MV Argos Reefer