



**ALS Inspection Chile SpA**  
 Lirache 3495, Office 61  
 Viña del Mar, CHILE  
 T +56 32 2545 500

Informe: IQQ-2602-0687  
 Fecha: February 16, 2026

This is to certify what we, **ALS Inspection CHILE SpA** did, at the request of Messrs. **Ecos Muellaje** stevedores, the undersigned surveyor attended onboard:

**"M/V MORNING PEACE"**

On February 16, While the vessel was berthed alongside pier Nr. 2, Empresa Portuaria de Iquique (EPI/Iquique/CHILE), for the purpose of carrying out an:

**"Arrival Condition Certificate"**

Brand	Chassis	Observation
CAT	X04221	Chopped windshield, used
TOYOTA	038088	Dented left side, used
MITSUBISHI	526295	Chopped windshield, used
MAZDA	103342	Dented front left fender, used

**ALS Inspections Remarks:** ALS Inspections inspected all the cargo on board. This Arrival Certificate only shows those new and second hand vehicles that arrived with some observations during our inspection.

**Chief Officer's Remark:**



**GONZALO BAGIAN VALDIVIA**  
 Surveyor  
 ALS INSPECTION CHILE SpA

*[Handwritten Signature]*  
 RECEIVED ONLY

**"M/V MORNING PEACE V - 601"**  
 Chief Officer

**M/V MORNING PEACE**  
 For Wilhelmsen Ship Management (Korea) Ltd.  
 For & on behalf of Owners, as Agents only