



This is to certify what we, **ALS Inspection CHILE SpA** did, at the request of Messrs. **Ecos Muellaje** stevedores, the undersigned surveyor attended onboard:


"M/V POLARIS HIGHWAY"

On May 30, While the vessel was berthed alongside pier Nr. 2, Empresa Portuaria de Iquique (EPI/Iquique/CHILE), for the purpose of carrying out an:


"Arrival Condition Certificate"

Brand	Chassis	Observation
Subaru	035217	Scrath on right side rear door

ALS Inspections Remarks: ALS Inspections inspected all the cargo on board. This Arrival Certificate only shows those new and second hand vehicles that arrived with some observations during our inspection.

Chief Officer's Remark: *FOUND AFTER DISCHARGING* 


MARIA JOSE PALMA C.
Surveyor
ALS INSPECCION CHILE SpA


"M/V POLARIS HIGHWAY V-92A"
Chief Officer