

February 16th, 2026

MIN-2602-0702

Certificate of Inspection

SERVICES			
Sampling		Port Control	
Weighing		Reception	
Moisture Determination		Consolidation	
Sample's preparation		Stock Inspection + HC	✓

GENERAL INFORMATION	
Client	: Ocean Partners
Clients reference	: P 31400.01
ALS Reference	: MIN-2602-0702
Place of Inspection	: Fundición Hernan Videla Lira.
Date of Attendance	: February 16 th , 2026
Material	: Mineral Fundicion Directa
Surveyor	: ALS Inspection Chile SpA
Inspector	: Benjamin Concha

Scope

- Our company was nominated by Ocean Partners to perform a visual verification of the merchandise declared as Mineral Fundicion Directa and its storage condition at the Hernan Videla Lira Smelter facilities, Paipote, Copiapó, Atacama Region-Chile.

Visual Inspection

- A visual inspection was carried out on the copper ore presented, which was found in bulk and stacked in the yard called "Cancha de Minerales".
- The material had a particle size no larger than 3.0 inches, presented in one pile showing different coloration. Located at a storage yard with concrete floor and at open air.

Weight (as declared)

Amount (MT) As declared
280 WMT

JOSE GALAN TRUJILLO ALIAGA
Gerente de Operaciones Minerales

ALS Inspection Chile





February 16th, 2026

MIN-2602-0702

Photoreport





ALS Inspection Chile SpA

Limache 3405, Office 61

Viña del Mar, CHILE

February 16th, 2026

MIN-2602-0702

