



ALS Inspection Chile SpA
 Limache 3405, Office 61
 Viña del Mar, CHILE
 T +56 32 2545 500
 Ref: THO-2601-0185

SEALING CERTIFICATE

M/V : ARGOS REEFER
 IMO Number : 9184548
 Flag : BAHAMAS
 Port : CORONEL / CHILE
 Date : JANUARY 23, 2025.

This is to certify that following seals have been fitted on Cooling Room, Hatch Covers and Manholes covers upon loading completed.

Hold Nr.	1	Hold Nr.	2
Hatch cover	80771 / 80772	Hatch cover	80512 / 80513
Manhole cover	80740	Manhole cover	80514
Cooling Room Door A	80510	Cooling Room Door A	80515
Cooling Room Door B	80502 / 80506 / 80507	Cooling Room Door B	80503
Cooling Room Door C	80504 / 80505	Cooling Room Door C	80741/80742/80743
-	-	Cooling Room Door D	80744/80745

Hold Nr.	3	Hold Nr.	4
Hatch cover	80517/80518	Hatch cover	80773/80774
Manhole cover	80519	Manhole cover	80775
Cooling Room Door A	80520	Cooling Room Door A	80747
Cooling Room Door B	80726	Cooling Room Door B	80748
Cooling Room Door C	80727/80728/80729	Cooling Room Door C	80749/80551/80552
Cooling Room Door D	80730/80746	Cooling Room Door D	80553/80554

Seals fitted on hatch covers, cooling room and manholes covers.


Mr. Oscar Arriagada C.
 ALS Inspection Chile
 Surveyor




 Master or C/O
 MV ARGOS REEFER