



**I. VESSEL**



1. M/V ARIES MIZUKI berthed at Punta Chungo Port.

**II. HOLD CONDITION**



2. Hold Nr. 5, general condition of bulkhead/Fwd.



3. Hold Nr. 5, general condition of bulkhead/Aft.



4. Hold Nr. 5/Ps, shell plating condition.



5. Hold Nr. 5/Ss, shell plating condition.



6. Hold Nr. 5, general condition of tank top plating.



7. Hold Nr. 5, bilge/Ss clean and dry.



8. Hold Nr. 5, bilge/Ss covered with burlap and sealed with tape.



9. Hold Nr. 5, bilge/Ps clean and dry.



10. Hold Nr. 5, bilge/Ps covered with burlap and sealed with tape.



11. Hold Nr. 5, Stevedores' access with rubber packing in good conditions.



12. Hold Nr. 5, non-return valve.



13. Hold Nr. 5, drain hole condition.



14. Hold Nr. 5, compression bar in good condition.



15. Hold Nr. 5, acting cleat.



16. Hatch cover hold Nr. 5, rubber packing condition.



17. Hold Nr. 5, hydraulic system without leaking.

### III. CONDITION OF CARGO



18. View of stockpile warehouse.



19. Copper concentrate inside stockpile prior commencement of loading operation.



#### IV. LOADING OPERATION



20. Ship loader system.



21. Conveyor belt.



22. Loading operation of copper concentrate in hold Nr. 5 commenced.



23. Loading operation in process in hold Nr. 5.



24. Loading operation completed in hold Nr. 5.

25. Loading operation completed in hold Nr. 5.

## V. SEALING OF HOLD AND STEVEDORES' ACCESS



26. General view of hatch covers sealed.



27. Hold Nr. 5, hatch cover with seal Nr. **ALS 00221**.



29 ene. 2026

28. General view of stevedores' access Fwd sealed.



29 ene. 2026

29. Hold Nr. 5, stevedores' access Fwd with seal Nr. **ALS 00222**.



29 ene. 2026

30. General view of stevedores' access Aft sealed.



29 ene. 2026

31. Hold Nr. 5, stevedores' access Aft with seal Nr. **ALS 00223**.



## VI. SHORE SCALE



32. Shore scale in zero check (prior to start loading operation).



33. Weighing scale before commence loading operation in hold Nr. 5 (first part).



34. Weighing scale after finishing loading operation in hold Nr. 5 (first part).



35. Weighing scale before commence loading operation in hold Nr. 5 (second part)



36. Weighing scale after finishing loading operation in hold Nr. 5 (second part).

## VII. SAMPLING OPERATION



37. Sample in plastic bags duly sealed by AHK personnel.



38. Sample in laboratory being poured into a tray of 52 x 60cm.



39. Sample being divided by AHK Lab personnel.



40. Sample divided in 20 square portions for filling the tray.



41. Sample being put into tray.



42. Weighing of tray with sample.



43. Trays being placed into the oven for 5 hours plus 1 hour.



44. View of trays with samples into the oven.



45. Oven closed by AHK lab personnel.



46. Oven temperature of 107.0 °C.




47. Sieve in process.



48. Sample being homogenized onto a carpet by AHK lab personnel.



49. Dried sample being divided into automatic divider.



50. Sample being put into aluminium bag.



51. Sample being sealed by AHK personnel.



52. Close up view of bag duly sealed/ labeled by AHK personnel.



53. Sample bags being sealed with ALS tape by ALS Surveyor.



54. General view of samples with ALS tape.



2 feb. 2026

55. Close up view of bag duly sealed with ALS tape.



29 ene. 2026

56. Informative poster reads "RESTRICTED AREA, AUTHORIZED PERSONNEL ONLY".

### VIII. INSPECTION EQUIPMENT AND SURROUNDING AREA UPON COMPLETION LOADING OPERATION (authorized only for this time by Punta Chungo Port)



29 ene. 2026

57. Shiploader without spilling of cargo.



29 ene. 2026

58. Vessel deck without spilling of cargo.



59. Conveyor belt clean and without spilling of cargo.



29 ene. 2026

60. Payloader clean and without spilling of cargo.



29 ene. 2026

61. Payloader clean and without spilling of cargo.



29 ene. 2026

62. Inside of stockpile was observed in process of reception for new cargo to be loading in the next vessel.



## IX. DISPATCHING OF SAMPLES



63. Sample bags being prepared to be placed inside carton box for SGS Netherlands B.V.



64. Sample bags packaged inside carton box to be dispatched to SGS Netherlands B.V.



65. Label with detail inside box to be dispatched to SGS Netherlands B.V.



66. Carton box duly labeled & closed to be dispatched to SGS Netherlands B.V.



67. Sample bags being prepared to be placed inside carton box for ALS UK.



68. Sample bags packaged inside carton box to be dispatched to ALS UK.



69. Label with detail inside box to be dispatched to ALS UK.



70. Carton box duly labeled & closed to be dispatched to ALS UK.



71. Sample bags being prepared to be placed inside carton box for Zhao Jingru.



72. Sample bags packaged inside carton box to be dispatched to Zhao Jingru.



73. Label with detail inside box to be dispatched to Zhao Jingru.



74. Carton box duly labeled & closed to be dispatched to Zhao Jingru.