



ALS Inspection Chile SpA  
Limache 3405, Office 61  
Viña del Mar, CHILE  
T +56 32 2545 500

Report: VAP-2605-1765  
Date: May 11, 2026

# INSPECTION OF CONTAINER STRUCTURAL CONDITION BEFORE STUFFING OPERATION

**ALS INSPECTION REFERENCE**

VAP-2605-1765

**INSPECTION ON BEHALF OF**

Bertling Logistics Chile S.A.

**REQUESTED BY**

Mr. Ariel Valdenegro

**CONTAINER 20" Nr.**

TCIU 400266-4

**DATE MANUFACTURED**

August 2024

**ALS SURVEYOR**

Alexander Luzardo I.

**PLACE OF INSPECTION**

Servicontainers S.A., Placilla, Valparaiso - Chile

**ATTENDANCE DATE**

May 11, 2026




Question	Answer
CONTAINER COMPLIANCE CHECKLIST FOR IMPORT/EXPORT OF EXPLOSIVES	Container Selection
<b>1.- General Requirements</b>	
1.1.- Non-vented general purpose ISO container	Compliance
1.2.- Valid CSC approval plated fitted or equivalent (ACEP No. legible)	Compliance
1.3.- Owners serial No. On CSC plate and container	Compliance
<b>2.- Doors</b>	
2.1.- Only two openings	Compliance
2.2.- Each door with two locking bars (ie. 4)	Compliance
2.3.- Door hinges serviceable and operative	Compliance
2.4.- Doors capable of being locked	Compliance



2.5.- Gaskets and seals in good condition	Compliance
2.6.- Weather tight	Compliance
<b>3.- External</b>	
3.1.- Top and bottom side rails	Compliance
3.2.- Top and bottom end rails	Compliance
3.3.- Door sill and header	Compliance
3.4.- Corner posts	Compliance
3.5.- Corner fittings	Compliance
3.6.- Side and end walls weathertight	Compliance
<b>4.- Internal</b>	
4.1.- Free of residue from previous cargo	Compliance
4.2.- Free from rust and scale	Compliance



4.3.- In clean condition	Compliance		
4.4.- Free of projections or protrusions	Compliance		
Remark: The lining specified is not required where all of the explosives in the container are in packaging's having substantial wooden outside surfaces or all the explosives are of Blasting Type E (UN0241, UN0332), in which case non lined steel containers may be used			
References: IMDG Section 7.4.6.4.2, CSC Code, Australian Explosives Code Section 6.3.			
CONCLUSION	APPROVED		
CONTAINER SEAL	ALS 2921471		
Date & Time of Survey	May 11, 2026 - 15:10 to 15:22 Hrs.		
This survey was carried out without prejudice and in the interest of whom it may concern.			
SURVEYOR	Alexander Luzardo I.	May 11, 2026	





## PHOTOGRAPHIC SET



1. General view of unit 20'



2. CSC plate



3. Side panel in good condition.



4. Front panel, front header, front sill, pillar and corner fitting in good condition.




5. Tight test.



6. Inside without damage.



7. Container floor in good conditions.



8. Container sealed with plastic seal  
Nr.2921471